

CERTIFICATE OF QUALITY

Material used: MSI Steel PS001

MSI-Forks certifies that the supplied forks were manufactured and tested in accordance with the quality standards of ISO 2330:2002 to handle the load capacity as stamped on the fork (s). This stamping can be located on the upper right side on the shank.


MSI-Forks guarantees the repair or replacement of the forks within 1 year from the date of invoice against any defect, failure, deformity or workmanship to the product.

MSI-Forks reserves the right to assess the fork (s) that appear to be defective and decide whether the defect, failure or deformity is pre-existing or caused by misuse of the product. As well, MSI-Forks reserves the right to decide whether the defect is liable to repair / fix or if there is need for replacement based on ISO 5057.


Warranty claim procedure:

- If the fork (s) appear to be defective **STOP USE IMMEDIATELY** and contact MSI at 888-789-3800.
- All Warranty claims must return the matching fork pair that appears to have the defect, along with the completed warranty claim sheet.
- Any changes or modifications made to the fork (s) without prior permission from MSI-Forks, may result in loss of load capacity and the product warranty.

To certify the authenticity of the MSI-Forks; please check the two points below and confirm:



MSI-Forks stamped on the top hook



MSI-Forks and lot number stamped on the side of the fork.

Contact us at:

803-980-6800

sales@msiforksinc.com

For more information:

www.msiforksinc.com